

Refill Instructions - HP 51626A (No.26)

HP	2276, 2277, 2279.
DesignJet	200, 220, 600, Plotter.
Deskjet	400, 420, 500, 510, 520, 540, 550, 560.
Deskwriter	400, 500, 520, 540, 550, 560.
Fax	200, 300, 310, 700, 750, 900, 950.
OfficeJet	300, 330, 350, LX.
Panasonic	PD-4200, PX350, PX360, UF300, UF305, UF310, UF311, UF312, UF321, UF322, UF332, UF333.
Sharp	UX-1200, UX-1500, FO-1700, FO-3700

Items Required

Original HP 26 Cartridge, Syringe, Knife & Filling Tube
Cyan Ink 8ml, Magenta Ink 8ml, Yellow Ink 8ml

Instructions

1. The filler holes are located under the top of the cartridge, which must be removed before filling. The easiest way to remove this top is to carefully cut along the seal with a sharp instrument such as a penknife. (fig.1)
2. Once top has been removed, assemble syringe and steel filling tube and fill with correct colour ink. (fig.2)
3. Insert the steel filling tube into the correct filler hole, following the details in fig.2. For best results, push the steel filling tube directly into the hole making sure that the steel filling tube is straight and not at an angle. Keep pushing until the steel filling tube reaches the centre of the sponge. **IMPORTANT** - The cartridge contains a sponge and a slight resistance may be felt.
4. **SLOWLY** inject ink into the cartridge. When the ink overflows from filling hole or starts to leak from print heads, cartridge is full.
5. Blot the print head to remove any excess ink and clean syringe with water before continuing to fill next colour. Ensure syringe is dry before refilling with ink.
6. After refilling the top can be replaced and secured using strong adhesive tape. The best way to secure the top is to stick the tape from one side, over the top and down the opposite side.
7. Leave cartridge to stand on a protective, non-absorbent surface overnight to ensure no further leakage and to give the ink time to fully saturate the sponge.

IMPORTANT - DO NOT LEAVE ON TISSUE

8. Install cartridge and run a priming cycle.

IMPORTANT - For best results, refill whilst cartridge still contains some ink. Empty cartridges should be refilled immediately.



fig.1



fig.2

